

Konica Minolta C35

How to view/print the Metre Reading

1. Press the 'Utility/Counter' button on the control panel.
2. Select 'user settings'.
3. Select 'print setting'.
4. Select 'print reports'.
5. push the down arrow key and select 'counter list print'.
6. You should then have printed the metre reading sheet.

I will need the TOTAL colour prints/copies and the TOTAL black and white prints/copies.